



Company	Trenz Electronic GmbH
PCN Number	PCN-20180911
Title	PCN-20180911 TE0714-02-*-2IC6 SPI Flash Change
Subject	BOM change
Issue Date	2018-09-11

Products Affected

This change affects Trenz Electronic TE0714-02 SoMs: TE0714-02-*-2IC6.

Affected Product	Replacement
TE0714-02-35-2IC6	TE0714-02-35-2IAC6
TE0714-02-50-2IC6	TE0714-02-50-2IAC6

Changes

#1 Change SPI Flash from N25Q128A11ESE40G to MT25QU128ABA1ESE-0SIT


Type: BOM change



Reason: N25Q128A11ESE40G became obsolete.

Impact: JEDEC ID changed from BB18h to BA18h.

Method of Identification

Locate Flash on topside of PCB:



N25Q128A11ESE40G	MT25QU128ABA1ESE-0SIT
	

Production Shipment Schedule

From September 2018, after old stock is gone.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20180911)
- phone
 - national calls: 05223 65301-0
 - international calls: 0049 5223 65301-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.