

SmartFusion2/IGLOO2 Fabric Lab Guide



a  **MICROCHIP** company

Microsemi PRO BU, San Jose, CA 95134

© 2019 Microsemi Corporation. All rights reserved.

Printed in the United States of America

Release: March 2019

Microsemi makes no warranties with respect to this documentation and disclaims any implied warranties of merchantability or fitness for a particular purpose. Information in this document is subject to change without notice. Microsemi assumes no responsibility for any errors that may appear in this document.

This document contains confidential proprietary information that is not to be disclosed to any unauthorized person without prior written consent of Microsemi Corporation.

Trademarks

Microsemi, SmartFusion2, IGLOO2 and the associated logos are trademarks or registered trademarks of Microsemi Corporation. All other trademarks and service marks are the property of their respective owners.

Table of Contents

Table of Contents.....	3
Introduction	4
Components Used in the Design	4
Tutorial Requirements.....	5
Extracting the source files.....	5
Step 1 – Creating the Design	5
Launching Libero SoC and creating a project.....	5
Implementing the design with SmartDesign	11
Step 2 - Simulating the design.....	19
Step 3 – Editing the I/O Physical Constraint file	25
Step 4 - Generating Timing Constraints	27
Step 5 – Synthesis and Layout	28
Step 6 – Programming	32
Running the Application	33
Step 7 - Debugging with SmartDebug	34
SmartDebug Live Probes.....	34
SmartDebug Active Probes	36
Record answers to questions below	39
Answers to Questions (results can slightly vary on your system)	40
List of Figures	41

Introduction

This tutorial demonstrates how to implement a basic SmartFusion2 / IGLOO2 FPGA fabric design using SmartDesign.

The design drives several LEDs on the SmartFusion2 or IGLOO2 target board. A counter output is used to drive the LEDs. The SmartDebug Live Probes are used to drive another LED on the target board.

After completing this tutorial, you will be familiar with the following:

- Creating a Libero SoC project
- Implementing a SmartFusion2 / IGLOO2 fabric design with SmartDesign
- Simulating the design
- Importing a PDC file, running layout and programming the SmartFusion2 / IGLOO2 silicon
- Using the SmartDebug Live Probes

Components Used in the Design

This tutorial uses the SmartFusion2 / IGLOO2 FPGA fabric, the on-chip 25/50 MHz RC oscillator and the Fabric CCC and Live Probe A.

Tutorial Requirements

Software Requirements

This tutorial requires the following software installed on your computer:

- Microsemi Libero SoC v12.0

Hardware Requirements

This tutorial can be used with the following SmartFusion2 board:

- SMF2000 SmartFusion2 board

Note: The Free Libero Silver license can be used with this kit.

Extracting the source files

Extract *SF2_Fab_Probe.zip* to extract the required lab files to the <C: or D:>|*Microsemiprj* folder on the HDD of your PC. Confirm that a folder named *SF2_Fab_Probe* containing a sub-folder named *Source_files* was extracted.

Step 1 – Creating the Design

In this step you will create the fabric design using SmartDesign. Some source files have been provided in the *Source_files* folder.

Launching Libero SoC and creating a project

1. Click **Start > Programs > Microsemi > Libero SoC v12.0**, or click the shortcut on your desktop. The Libero SoC Project Manager will open.




Figure 1 - Libero SoC Project Manager

2. Create a new project by selecting **New** on the Start Page tab (circled in the figure above), or by clicking **Project > New Project** from the Libero SoC menu. The New Project wizard will open.




Figure 2 - Libero SoC New Project dialog box

3. Enter the information shown below in the Project Details page of the New Project dialog box then click **Next**:

- Project Name: SmartFusion2_Fabric
- Project Location: <C: or D:>\Microsemiprj\SF2_Fab_Probe (depending on where you extracted the source files)
- Preferred HDL type: Verilog or VHDL, select VHDL for this lab example
- Enable Block Creation: un-checked




Figure 3 - Project Details

4. Enter the following in the Device Selection page of the New Project dialog box, select M2S010-VF400 device then click **Next**:

- Family: SmartFusion2
- Die: M2S010
- Package: 400 VF
- Speed: STD
- Core Voltage(V): 1.2
- Range: COM




Figure 4 - Device selection (settings for SMF2000 board shown)

5. Enter the following in the Device Settings page of the New Project dialog box then click **Next**:

- Default I/O Technology: **LVC MOS 3.3V**
- Reserve Pins for Probes: checked (default)
- Power Supplies
 - PLL Supply Voltage (V): **3.3V**
 - Ramp rate: 100ms (default)
 - System Controller Suspend Mode: un-checked

The PLL Supply voltage can be either 2.5V or 3.3V. The voltage setting in the New Project dialog box must match the PLL Analog Supply voltage on the board to ensure the PLL works correctly.




Figure 5 - Device Settings (settings for SMF2000 board shown)

6. Enter the following in the Design Template page of the New Project dialog box then click **Next**:

- Design Templates and Creators: **None** (this design does not use the SmartFusion MSS or IGLOO2 HPMS)
- Design Methodology:
 - Use Standalone Initialization for MDDR/FDDR/SERDES peripherals: un-checked
 - Instantiate SystemBuilder/MSS component in a SmartDesign on creation: checked




Figure 6 - Design Template settings (all kits)

7. The Add HDL Source Files page will be visible. A VHDL source file has been provided. Import the file into the project by clicking **Import File**.
8. Enter the following in the Import Files dialog box then click **Open**:
 - Location: <C or D:>\Microsemiprj\SF2_Fab_Probe\Source_files
 - File name: count24.vhd
 - Files of type: HDL Source Files (*.vhd *.v *.h)




Figure 7 - Imported HDL source files

9. Click **Next**. The Add Constraints page will be visible. An I/O constraint file has been provided. Import the file into the project by clicking **Import File**.

10. Enter the following in the Import Files dialog box then click **Open**:

- Location: <C or D:>\Microsemiprj\SF2_Fab_Probe\Source_files
- File name: Fabric_Top.pdc
- Files of type: I/O Constraint Files (*.pdc)




Figure 8 - Imported I/O Constraint file

11. Click **Finish** in the New Project dialog box.

12. The HDL source file will be visible on the Design Hierarchy tab after clicking **Build Hierarchy**. Both the HDL source file and the I/O constraint file will also be visible on the Files tab.




Figure 9 - HDL source file and I/O constraint file in Libero SoC

Implementing the design with SmartDesign

1. Open the SmartDesign canvas by selecting **File > New > SmartDesign** from the menu or by double-clicking **Create SmartDesign** under Create Design on the Design Flow tab.




Figure 10 - Opening the SmartDesign canvas

2. Enter *Fabric_Top* in the Create New SmartDesign dialog box then click **OK**. Save the component with **CTRL+SHIFT+S**.



Figure 11 - Entering SmartDesign name

3. Click **Build Hierarchy** & Drag the count24 component from the Design Hierarchy tab to the SmartDesign canvas.

This design uses a fabric CCC to generate the 1 MHz internal clock. The CCC reference clock is the 25/50 MHz RC oscillator. In the next steps you will configure the CCC to output a 1 MHz clock and configure the on-chip oscillator.

4. Expand **Clock & Management** in the IP catalog.




Figure 12 - Clock & Management category of the Libero SoC IP Catalog

5. Drag an instance of the Clock Conditioning Circuitry (CCC) v2.0.201 component into the SmartDesign canvas.
6. FAB CCC Configurator will open, otherwise double-click the FCCC_0 component in the SmartDesign canvas to open the FAB CCC Configurator.

7. Select the Basic tab in the FAB CCC configurator. Enter the following:

- Reference clock: Select Oscillators > 25/50 MHz Oscillator from the pull-down menu
- GL0: checked;
- Exact Value: checked
- Frequency: 1 MHz




Figure 13 - Configuring the fabric CCC

8. Click **OK** to close the FAB CCC Configurator.
9. Drag an instance of the Chip Oscillators v2.0.101 component from the IP catalog into the SmartDesign canvas.
10. Chip Oscillators Configurator will open, otherwise double-click the OSC_0 component in the SmartDesign canvas to open the Chip Oscillators configurator.
11. Configure the 50 MHz RC oscillator to drive the fabric CCC as follows:
 - Enable the On-chip 25/50 MHz RC Oscillator
 - Select Drives Fabric CCC(s)




Figure 14 - Configuring the Chip Oscillators (SmartFusion2 target)

12. Click **OK** to close the Chip Oscillators configurator.
13. Expand **Macro Library** in the Libero SoC IP catalog.




Figure 15 – Macro Library category of the Libero SoC IP Catalog

14. Drag an instance of AND2 and SYSRESET into the SmartDesign Canvas.

Tip: to make it easier to find the macros listed above, type a few letters of the macro name followed by * in the IP Catalog search field. When finished, change the field to * to display the entire catalog.



Figure 16 - IP Catalog Search field

15. Drag an instance of LIVE_PROBE_FB into the SmartDesign Canvas. The LIVE_PROBE_FB macro allows the SmartDebug Live Probes to be re-directed into the FPGA fabric. One of the outputs will be connected to an LED on the target board.
16. After adding the components, the SmartDesign will resemble the figure below. If needed, drag the components to improve the appearance of the canvas.

Tip: expand the canvas area by selecting **View > Maximize Work Area** or click the icon on the tool bar ().




Figure 17 - SmartDesign canvas after adding components

Making connections in the canvas

Next connect the components in the SmartDesign canvas to complete the design. SmartDesign in Libero SoC has a connection mode that supports click, drag and release to make connections.

17. Select **SmartDesign > Connection Mode** from the Libero SoC menu or click the Connection Mode icon ().
18. Connect the RCOSC_25_50MHZ_CCC_OUT port of OSC_0 component to the RCOSC_25_50MHZ_CCC_IN port of the FCCC_0 component as follows:
 - Click and hold mouse button on the RCOSC_25_50MHZ_CCC_OUT port of the OSC_0 component.
 - Drag mouse to the RCOSC_25_50MHZ_CCC_IN port of FCCC_0 component.
 - Release mouse button on the RCOSC_25_50MHZ_CCC_IN port to make the connection.
19. Repeat the previous step to make the connections shown it the table below.

From	To
FCCC_0:GLO	count24_0:CLK
FCCC_0:LOCK	AND2_0:A
SYSRESET_0:POWER_ON_RESET_N	AND2_0:B
AND2_0:Y	count24_0:RESETn

Table 2 – SmartDesign canvas connections

20. Disable the SmartDesign connection mode by selecting **SmartDesign > Connection Mode** from the Libero SoC menu.
21. Promote the UP_DN port from count24_0 to the Top Level by selecting the UP_DN port and choosing **Promote to Top Level** from the popup menu (click right mouse button).
22. Rename UP_DN port to USER_BTN by choosing **Rename Top Level Pin** from the popup menu (click right mouse button).
23. Expose bits 16 to 23 of count24_0 by selecting port Q[23:0] of count24_0 then right-clicking and selecting **Edit Slice**.




Figure 18 - Adding a slice to the Q[23:0] output

24. Click the + sign (circled in the figure below) in the Edit Slices – Q[23:0] dialog box.




Figure 19 - Edit Slices dialog box

25. Enter 23 for the Left and 16 for the Right index to expose count24_0[23:16] and click **OK**.




Figure 20 - Adding a slice to the count24_0 output

26. Mark the PROBE_B port of the LIVE_PROBE_FB_0 component unused by selecting the port then right-clicking and selecting **Mark Unused**.



Figure 21 - Marking the PROBE_B port unused

27. Right-click anywhere in Design Canvas and select “Add Port”. The Add Port dialog box will appear.




Figure 22 – Adding a port in Design Canvas

28. Enter the following in the Add Port dialog box then click **OK**:

- Name: LED[7:0]
- Direction : Output




Figure 23 – Adding LED[1:8] output port in Design Canvas

29. If required, click the + sign on the Q[23:0] port of count24_0 to expose the slice that was created above.

30. Connect the Q[23:16] port of count24_0 to the LED[7:0] output port.

31. Add another output port called USER_LED.

32. Connect the PROBE_A port of the LIVE_PROBE_FB_0 component to the USER_LED output port.

33. After making the connections listed above the SmartDesign canvas will appear as shown in the figure below. You can drag the components or use the SmartDesign Auto Arrange feature to improve the appearance of the canvas.




Figure 24 - SmartDesign canvas after making connections

34. Save the design (**File > Save Fabric_Top**).
35. Generate the design by clicking **SmartDesign > Generate Component** or by clicking the Generate Component icon on the SmartDesign toolbar ().
36. Restore the work area (**View > Restore Work Area**) if you expanded the work area earlier.
37. Confirm that the message “Fabric_Top' was successfully generated” appears in the Libero Log window. The warning message “Floating output bus pin count24_0:Q[23:0]” can be ignored.
38. Close the design (**File > Close Fabric_Top**).

Step 2 - Simulating the design

The next step is to simulate the design. A testbench, ModelSim macro file and a wave format file have been provided in the source files. The LED_ctrl module/entity contains a 24 bit counter. With the slow clock rate (1 MHz) simulation would take a long time. In order to accelerate the simulation of the design some of the counter bits are forced high in the ModelSim macro file during a second phase of the simulation.

1. Confirm that Fabric_Top appears in bold font in the Libero Design Hierarchy window after clicking **Build Hierarchy**. If it does not, select Fabric_Top, right-click and select **Set As Root**.




Figure 25 - Setting Fabric_Top as the root level

2. Expand Verify Pre-Synthesized Design in the Design Flow window. Right-click **Simulate** and select **Import Files**.




Figure 26 - Importing the testbench

3. Import the ModelSim macro file and Wave format file.
4. Enter the following in the Import Files dialog box then click **Open**:
 - Look in: <C: or D:>\Microsemiprj\SF2_Fab_Probe\Source_files
 - Files of type: Simulation Files (*.mem *.bfm *.dat *.txt *.do)
 - File name: Hold the shift key and select vhdl_run.do and vhdl_wave.do




Figure 27 - Importing the simulation files

5. Import the testbench by right-clicking **Simulate** under Verify Pre-Synthesized Design in the Design Flow window and selecting **Import Files**.
6. Enter the following in the Import Files dialog box then click **Open**:
 - Look in: <C: or D:>\Microsemiprj\SF2_Fab_Probe\Source_files
 - Files of type: HDL Stimulus Files (*.vhd *.v)
 - File name: user_testbench.vhd




Figure 28 - Importing the testbench

7. Select the Stimulus Hierarchy tab & click **Build Hierarchy**. The testbench (user_testbench.vhd) will be visible. Select the testbench, right-click and select **Set As Active stimulus**. A waveform symbol will indicate the active stimulus (circled below).

Note: If user_testbench.vhd is not visible on the Stimulus Hierarchy tab, the file was not imported as an HDL stimulus file. Re-import the file as described above.




Figure 29 - Testbenches in the SmartFusion2_Fabric project

The testbench and simulation files will be visible on the Libero SoC Files tab under Stimulus and Simulation.




Figure 30 - Testbench and simulation files

8. Open the ModelSim macro file (vhdl_run.do) in the Libero SoC editor by double-clicking the filename on the Files tab.
9. Locate the variable PROJECT_DIR on line 15 of vhdl_run.do and confirm that it matches the location of your Libero SoC fabric tutorial. The location is displayed at the top of the Libero SoC GUI (do not include "SmartFusion2_Fabric.prjx"). Edit the path if necessary.




Figure 31 - Location of Libero SoC project

10. Locate the variable INSTALL_DIR on line 17 of vhdl_run.do and confirm that it matches the location of your Libero SoC installation. Edit the path if necessary. Ask the lab instructor if you do not know the Libero SoC installation path.
11. If you made changes, save the file (**File > Save vhdl_run.do**).
12. Scroll in the file to become familiar with the commands it contains. The command force –freeze forces some of the counter bits in LED_ctrl high to speed up the simulation in the second phase of the simulation.
13. Close the editor (**File > Close vhdl_run.do**).
14. Open the Libero SoC project settings (**Project > Project Settings**).




Figure 32 - Libero SoC Project Settings dialog box (settings for SF2PLUS-DEV-KIT board shown)

15. Select Do File under **Simulation Options** in the Project Settings Dialog box.

16. Un-check “Use automatic DO file”.

17. Click the browse button ()next to “User defined DO file” and enter the following then click **Open**:

- Look in: <C: or D:>\Microsemiprj\SF2_Fab_Probe\SmartFusion2_Fabric\simulation
- Files of type: *.do
- File name: vhdl_run.do

The ModelSim macro file vhdl_run.do calls the Wave format file vhdl_wave.do, so there are no settings required for the Wave Format file.




Figure 33 - Simulation options

18. Click **Save** then **Close** to close the Project settings dialog box.

19. Select Project -> Tool Profiles...

In order to use a ModelSim tool version which is supported by the Silver license, a new Simulation profile has to be added.




Figure 34 - Tool Profiles

20. Select Simulation under Tools, click Add profile + button and enter settings below, then click OK:

- Name: ModelSim ME
- Tool integration: ModelSim
- Browse to Location and select: C:\Microsemi\Libero_SoC_v12.0\ModelSim\win32acoem\modelsim.exe




Figure 35 - ModelSim ME Profile

21. Make sure ModelSim ME is set as Active Simulation Profile, then press OK

22. Expand Verify Pre-Synthesized Design in the Design Flow window. Right-click **Simulate** and select **Open Interactively** to launch ModelSim in GUI mode.




Figure 36 - Launching pre-synthesis simulation

23. The simulation will run for 2.0 ms. When finished, the Wave window should appear as shown below after selecting **Zoom full** from the popup menu (click right mouse button inside Wave – Default window).




Figure 37 - ModelSim Wave window

24. Scroll in the wave window. The LED[7:0] port represents the LED driver (0 = LED off; 1 = LED on. The USER_LED port is the re-directed Live Probe output. In the simulation this appears as a Hi-Z signal. When SmartDebug is used, the output of any flip-flop can be re-directed to this output port.
25. Contact the lab instructor if your results do not match the figure above.
26. Close the ModelSim simulator (**File > Quit**). Click **Yes** when asked if you want to quit.

Step 3 – Editing the I/O Physical Constraint file

There are multiple ways to make I/O Assignments. In this lab we will use the I/O Physical Design Constraint (PDC) file that was imported when the project was created. The I/O pdc file must be edited to match the target board.

1. Double-click **Manage Constraints** in the Libero SoC Design Flow window to open the Libero SoC Constraint Manager.





Figure 38 - Libero SoC Constraint Manager

2. Select the Constraint Manager I/O Attributes tab. Double-click the Fabric_Top.pdc to open the file in the Libero SoC editor. Scroll in the file to become familiar with the syntax. The constraint set_iobank sets the input voltage of the bank to determine the allowable I/O standards; the constraint set_io sets the pin number and I/O specific attributes. The # symbol is a comment.



```

1 #-----#
2 # Company: Microsemi SoC Products Group
3 #
4 # File: Fabric_Top.pdc
5 # File history:
6 #   Rev 1.0 July 25, 2016    Written for SF2_Fab_Probe design
7 #   Rev 2.0 March 1, 2017    Added pinouts for Future Creative boards
8 #   Rev 2.1 May 8, 2017     Added pinouts for Avnet Kickstart board
9 #   Rev 2.2 Feb 22, 2018    Removed ES silicon
10 #
11 # Description:
12 # PDC constraint file which sets the I/O bank voltage settings and
13 # I/O pin assignments for the Microsemi SmartFusion2 Fabric / Probe tutorial
14 #
15 # Author: Tim McCarthy
16 #-----
17 # Pin assignments for SF2-484-STARTER-KIT with M2S010-FGG484 device OR
18 # SF2-STARTER-KIT with M2S050-FGG484 device
19 # Banks not listed use default setting of 2.5V
20 #set_iobank Bank0 -vcci 1.80 -fixed yes
21 #set_iobank Bank1 -vcci 3.30 -fixed yes
22 #set_iobank Bank2 -vcci 3.30 -fixed yes
23 #set_iobank Bank3 -vcci 3.30 -fixed yes

```

Figure 39 - PDC file in the Libero SoC constraint editor

A description of the Designer PDC constraints is available in the Libero Help (**Help > Help Topics > Manage Constraints > Assigning Design Constraints > Design Constraints Guide > Reference > Constraints by File Format > PDC Command Reference**).

For more information regarding pin assignments for the SmartFusion2 target board, refer to the schematic for the board, which is available from the Trenz Electronic website (http://www.trenz-electronic.de/fileadmin/docs/Trenz_Electronic/Modules_and_Module_Carriers/2.5x6.15/TEM0001/REV01/Documents/SCH-TEM0001-01-010C.PDF).

3. All the assignments in the PDC file are commented. Uncomment the lines starting with **set_iobank** and **set_io**.
4. Save the PDC file after making modifying (**File > Save Fabric_Top.pdc**).
5. Close the PDC file (**File > Close Fabric_Top.pdc**).
6. Check Fabric_Top.pdc for **Place and Route** on the I/O Attributes tab of the Libero Constraint Manager.




Figure 40 - Selecting the I/O PDC constraint file in the Design Flow window

Step 4 - Generating Timing Constraints

In this step you derive timing constraints for the design. Timing constraints for known blocks (such as the RC oscillators and the PLLs) can be generated automatically.

1. Select the Timing tab in the Constraint manager window. Click on **Derive Constraints**.




Figure 41 - Deriving Timing Constraints

2. Click on **Yes** in the Message window to automatically associate the derived constraints SDC file to the 'Synthesis', 'Place and Route' and 'Timing Verification'.




Figure 42 - Message Window

3. Double click on the Top_derived_constraints.sdc to view the automatically generated clock constraints in the text editor.





Figure 43 - Derived Timing Constraints

4. For this design a Clock constraint and Generated Clock constraint are generated automatically. The Clock constraint is the constraint for the 50 MHz RC oscillator, which is the reference clock for the fabric CCC. The Generated Clock constraint is the constraint for the 1 MHz Fabric PLL output.



```

1 # Microsemi Corp.
2 # Date: 2018-Nov-08 16:15:12
3 # This file was generated based on the following SDC source files:
4 # D:/Microsemiprj/SF2_Fab_Probe/SmartFusion2_Fabric/component/work/Fabric_Top/FCCC_0/Fabric_Top_FCCC_0_FCCC.sdc
5 # D:/Microsemiprj/SF2_Fab_Probe/SmartFusion2_Fabric/component/work/Fabric_Top/OSC_0/Fabric_Top_OSC_0_OSC.sdc
6 # C:/Microsemi/Libero_SoC_v11.9/Designer/data/aPA4M/cores/constraints/sysreset.sdc
7 #
8 #
9 create_clock -name {OSC_0/I_RCOSC_25_50MHZ/CLKOUT} -period 20 [ get_pins { OSC_0/I_RCOSC_25_50MHZ/CLKOUT } ]
10 create_generated_clock -name {FCCC_0/GL0} -multiply_by 2 -divide_by 100 -source [ get_pins { FCCC_0/CCC_INST/RCOSC_25_50MHZ }
11 set_false_path -ignore_errors -through [ get_pins { SYSRESET_0/POWER_ON_RESET_N } ]
12

```

Figure 44 - Derived timing constraints

5. Close the Constraint Manager Editor (**File > Close Top_derived_constraints.sdc**).

Step 5 – Synthesis and Layout

In this step you will use the push-button flow to synthesize the design with Synplify Pro, run layout and generate the programming file.

1. Double-click the Generate Bitstream in the Design Flow window to synthesize the design, run layout and generate the programming file.




Figure 45 - Generate Bitstream

The design implementation tools will run in batch mode. Successful completion of a design step will be indicated by a green check mark next to the Implement Design item in the Design Flow window.




Figure 46 – Successful completion of design implementation

2. The Reports tab will display reports for the tools used to implement the design.




Figure 47 - Reports tab after implementing the design

3. Select the Compile report (Fabric_Top_compile_netlist_resources.xml) under Synthesize on the Reports tab to view the resource usage. Record the number of combinatorial cells (LUTs) and sequential cells (Flip-flops) used in the design below.

LUTs (4LUT) _____

Flip-flops (DFF) _____

4. Generate a timing report by right-clicking Verify Timing under Verify Post Layout Implementation on the Design Flow tab and selecting Run.




Figure 48 - Generating the post-layout timing report

5. Select the timing report named Fabric_Top_max_timing_slow_1.14V_85C.xml under Verify Timing on the Reports tab. Scroll to the timing summary in the Report window. Record the maximum frequency for the clock FCCC_0/ GL0 below:

FCCC_0/ GL0: _____

6. Timing violations can quickly be identified by looking at the timing violations reports (Fabric_Top_max_timing_violations_slow_1.14V_85C.xml and Fabric_Top_min_timing_violations_fast_1.26V_0C.xml).
 7. The output files from Synplify Pro and Designer will be visible on the Libero SoC Files tab.




Figure 49 - Synthesis and Designer files on Libero SoC Files tab

Step 6 – Programming

In this step, you will run FlashPro in batch mode to program the SmartFusion2 device on the SmartFusion2 target board. Connect the SMF2000 board using a Micro-USB cable to the PC USB port (board power is provided from PC USB port).

1. Expand Program Design in the Design Flow window. Right-click **Run PROGRAM Action** and select **Run** to begin programming.




Figure 50 - Launching Programming software from Design Flow window

2. FlashPro will run in batch mode and program the device. Programming messages will be visible in the Libero SoC log window (programmer number and device number may differ).

Note: Do not interrupt the programming sequence; it may damage the device or the programmer.

3. The following message should be visible in the Reports view under Program Device when the device is programmed successfully (programmer number will differ; device will differ depending on the target board):

```
programmer '30237' : device 'M2S010' : Executing action PROGRAM PASSED.
```

```

All 0 Errors 1 Warning 0 Info

Software Version: 12.500.0.22
Embedded FlashPro5 programmer detected.
programmer 'E2002HTX2H' : FlashPro5
Opened 'C:\Microsemiprj\SF2_Fab_Probe\SmartFusion2_Fabric\designer\Fabric_Top\Fabric_Top_fp\Fabric_Top.pro'
The 'open_project' command succeeded.
Warning: Programming is already enabled for device 'M25010'.
The 'enable_device' command succeeded.
IPD file 'C:\Microsemiprj\SF2_Fab_Probe\SmartFusion2_Fabric\designer\Fabric_Top\Fabric_Top.ipd' has been loaded successfully.
DESIGN : Fabric_Top; CHECKSUM : 557E; PDB VERSION : 1.9
The 'set_programming_file' command succeeded.
The 'set_programming_action' command succeeded.
programmer 'E2002HTX2H' : Scan Chain...
programmer 'E2002HTX2H' : Scan and Check Chain PASSED.
programmer 'E2002HTX2H' : device 'M25010' : Executing action PROGRAM
programmer 'E2002HTX2H' : device 'M25010' : Family: Igloo2
programmer 'E2002HTX2H' : device 'M25010' : Product: M2GL005
programmer 'E2002HTX2H' : device 'M25010' : EXPORT ISC_ENABLE_RESULT[32] = 007af6a44
programmer 'E2002HTX2H' : device 'M25010' : EXPORT CRCERR[1] = 0
programmer 'E2002HTX2H' : device 'M25010' : EXPORT EDCERR[1] = 0
programmer 'E2002HTX2H' : device 'M25010' : Programming FPGA Array...
programmer 'E2002HTX2H' : device 'M25010' : =====
programmer 'E2002HTX2H' : device 'M25010' : EXPORT DSN[128] = 6aa516a986ffec4eb1c0d25cb924d9d0
programmer 'E2002HTX2H' : device 'M25010' : =====
programmer 'E2002HTX2H' : device 'M25010' : Finished: Fri Mar 15 15:20:15 2019 (Elapsed time 00:00:24)
programmer 'E2002HTX2H' : device 'M25010' : Executing action PROGRAM PASSED.
programmer 'E2002HTX2H' : Chain programming PASSED.
Chain Programming Finished: Fri Mar 15 15:20:15 2019 (Elapsed time 00:00:24)

o - o - o - o - o - o

The 'run_selected_actions' command succeeded.
The 'set_programming_file' command succeeded.
Project saved.
The 'save_project' command succeeded.
Project closed.
Exported log file C:\Microsemiprj\SF2_Fab_Probe\SmartFusion2_Fabric\designer\Fabric_Top\Fabric_Top_fp\Fabric_Top.log.
The 'close_project' command succeeded.
The Execute Script command succeeded.
  
```

Figure 51 - Programming messages in Libero SoC log window

4. A green check mark will appear next to Program Design and Run PROGRAM Action in the Design Flow window to indicate programming completed successfully.




Figure 52 - Design Flow window after programming

Running the Application

5. Reset the board by pressing and releasing the Reset button (the button on the opposite side of the LEDs) and observe the pattern of the LEDs.
6. Press the USER_BTN (the button near the 8 LEDs) and observe the counter changing the count direction.

Step 7 - Debugging with SmartDebug

In this step you will use SmartDebug to view internal circuits in the design.

SmartDebug tool is a new approach to debug the Microsemi FPGA array and SERDES without using an internal logic analyzer (ILA). SmartDebug provides the following methods to debug the SmartFusion2 / IGLOO2 FPGA array:

- **Live Probe:** Two dedicated probes can be configured to observe a Probe Point which is any input or output of a logic element. The probe data can then be sent to an oscilloscope or logic analyzer.
- **Active Probe:** Active Probe allows dynamic asynchronous read and write to a flip-flop or probe point. This enables a user to quickly observe the output of the logic internally or to quickly experiment on how the logic will be affected by writing to a probe point.
- **Memory Debug:** Memory debug is used to debug embedded FPGA fabric memories (uSRAM and LSRAM) by reading and writing to the memory block. Memory Debug also supports reading eNVM memory content.
- **Probe Insertion:** Probe insertion is used to insert probes into the design and bring signals out to the FPGA package pins to evaluate and debug the design.
- **SERDES Debug:** SmartDebug is used to debug high speed serial interfaces by utilizing on-chip PRBS features and signal integrity controls.

SmartDebug Live Probes

In this step we will use Live Probe A to drive one of the LEDs on the target board. The LIVE_PROBE_FB macro re-directs the Live Probe output. For this design we connected the PROBE_A output of the LIVE_PROBE_FB macro to an output pin which is connected to the USER_LED on the target board.

1. Expand Debug Design in the Libero Design Flow window. Select SmartDebug Design then right-click and select **Open Interactively**.




Figure 53 - Launching SmartDebug

2. The SmartDebug GUI will open. Click the Debug FPGA Array button (circled in the figure below). The Debug SERDES option may not be available for some target boards.




Figure 54 - SmartDebug GUI (SF2PLUS-DEV-KIT board shown)

4. Select the Live Probes tab in the **Debug FPGA Array** GUI. The design hierarchy is displayed in the left window. Signals selected for probing are displayed in the right window.




Figure 55 - SmartDebug Live Probes tab

5. Select **count24_0** in the Instance Tree on the Hierarchical View then click **Add**. The signals will appear in the Live Probes tab.




Figure 56 - count24_0 signals in the Live Probes tab

6. Select the signal LED_c[0]:count24_0/Q_int[16]:Q then click **Assign to Channel A**.
7. The USER_LED starts blinking.
8. Select a different signal and assign it to Channel A. Observe the change in the LED patterns. Live Probe allows observation of any flip-flop output without having to run layout on the design.
9. Try assigning a few other signals to Channel A and observe the results.

SmartDebug Active Probes

In this step, we will use the Active Probes to observe the output of count_24_0.

10. Select the Active Probes tab in the Debug FPGA Array GUI. The design hierarchy is displayed in the left window. Signals selected for probing are displayed in the right window.




Figure 57 - SmartDebug Active Probes tab

11. Select count24_0 in the Instance Tree on the Hierarchical View then click **Add**. The signals will appear in the Active Probes tab.




Figure 58 - Adding the count24_0 signals to the Active Probes tab

12. Click the **Read Active Probes** button (circled in the figure below). The state of the signal will be displayed. Clicking **Read Active Probes** repeatedly will allow observation of the counter output.




Figure 59 - Reading the counter with the Active Probes

13. Click **Close** to close the Debug FPGA dialog box. Click **Cancel** when prompted about saving the active probes.
14. Close SmartDebug (**File > Exit**) and Libero SoC (**Project > Exit**).

End of SmartFusion2 Fabric lab

Record answers to questions below

Name: _____

Page 34

Record the number of combinatorial and sequential cells used in the design below.

LUTs (4LUT) _____

Flip-flops (DFF) _____

Page 35

Record the maximum frequency for the clock FCCC_0/ GL0 below:

FCCC_0/ GL0: _____

Answers to Questions (results can slightly vary on your system)

Page 34

Record the number of sequential and combinatorial cells used in the design below.

4LUT 25

DFF 24

Page 35

Record the maximum frequency for the clock FCCC_0/GL0 below:

FCCC_0/ GL0: 431.965 MHz

List of Figures

Figure 1 - Libero SoC Project Manager	5
Figure 2 - Libero SoC New Project dialog box	6
Figure 3 - Project Details	6
Figure 4 - Device selection (settings for SMF2000 board shown)	7
Figure 5 - Device Settings (settings for SMF2000 board shown)	8
Figure 6 - Design Template settings (all kits)	8
Figure 7 - Imported HDL source files.....	9
Figure 8 - Imported I/O Constraint file	10
Figure 9 - HDL source file and I/O constraint file in Libero SoC	10
Figure 10 - Opening the SmartDesign canvas	11
Figure 11 - Entering SmartDesign name	11
Figure 12 - Clock & Management category of the Libero SoC IP Catalog	11
Figure 13 - Configuring the fabric CCC	12
Figure 14 - Configuring the Chip Oscillators (SmartFusion2 target)	13
Figure 15 – Macro Library category of the Libero SoC IP Catalog.....	13
Figure 16 - IP Catalog Search field	14
Figure 17 - SmartDesign canvas after adding components	14
Figure 18 - Adding a slice to the Q[23:0] output.....	15
Figure 19 - Edit Slices dialog box.....	16
Figure 20 - Adding a slice to the count24_0 output	16
Figure 21 - Marking the PROBE_B port unused	16
Figure 22 – Adding a port in Design Canvas.....	17
Figure 23 – Adding LED[1:8] output port in Design Canvas.....	17
Figure 24 - SmartDesign canvas after making connections	17
Figure 25 - Setting Fabric_Top as the root level	19
Figure 26 - Importing the testbench	19
Figure 27 - Importing the simulation files.....	20
Figure 28 - Importing the testbench	20
Figure 29 - Testbenches in the SmartFusion2_Fabric project	21
Figure 30 - Testbench and simulation files	21
Figure 31 - Location of Libero SoC project	21
Figure 32 - Libero SoC Project Settings dialog box (settings for SF2PLUS-DEV-KIT board shown)	22
Figure 33 - Simulation options	22
Figure 34 - Tool Profiles	23
Figure 35 - ModelSim ME Profile	23
Figure 36 - Launching pre-synthesis simulation.....	24
Figure 37 - ModelSim Wave window	24
Figure 38 - Libero SoC Constraint Manager	25
Figure 39 - PDC file in the Libero SoC constraint editor.....	26
Figure 40 - Selecting the I/O PDC constraint file in the Design Flow window	26
Figure 41 - Deriving Timing Constraints.....	27
Figure 42 - Message Window.....	27
Figure 43 - Derived Timing Constraints.....	27
Figure 44 - Derived timing constraints.....	27
Figure 45 - Generate Bitstream.....	28
Figure 46 – Successful completion of design implementation	29

Figure 47 - Reports tab after implementing the design.....	29
Figure 48 - Generating the post-layout timing report	30
Figure 49 - Synthesis and Designer files on Libero SoC Files tab	31
Figure 50 - Launching Programming software from Design Flow window.....	32
Figure 51 - Programming messages in Libero SoC log window	33
Figure 52 - Design Flow window after programming	33
Figure 53 - Launching SmartDebug.....	34
Figure 54 - SmartDebug GUI (SF2PLUS-DEV-KIT board shown).....	35
Figure 55 - SmartDebug Live Probes tab.....	35
Figure 56 - count24_0 signals in the Live Probes tab.....	36
Figure 57 - SmartDebug Active Probes tab	37
Figure 58 - Adding the count24_0 signals to the Active Probes tab.....	37
Figure 59 - Reading the counter with the Active Probes	38