

Company	Trenz Electronic GmbH
PCN Number	PCN-20201004
Title	TE0876-02 SPI Flash Change
Subject	BOM change
Issue Date	2020-10-06

1 Products Affected

This change affects all Trenz Electronic TE08760 modules of revision 02.

Affected Product	Replacement
TE0876-02	TE0876-02-A

2 Changes

2.1 #1 Change SPI Flash from N25Q064A13ESE40F to IS25LP064D-JBLE


Type: BOM change



Reason: Old flash is obsolete.

Impact: JEDEC ID changes from BA17h to 6017h and manufacturer ID from 20h to 9Dh.

3 Method of Identification

Locate Flash (U12) at top side of PCB:



N25Q064A13ESE40F	IS25LP064D-JBLE
	

4 Production Shipment Schedule

From mid November 2020, after old stock is gone. If still the old assembly variant is needed please contact us.

5 Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de¹
- wiki.trenz-electronic.de²
- support@trenz-electronic.de³ (subject = PCN-20201004)
- phone
 - national calls: 05223 65301-0
 - international calls: 0049 5223 65301-0

6 Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

¹ <http://forum.trenz-electronic.de/>

² <http://wiki.trenz-electronic.de/>

³ <mailto:support@trenz-electronic.de?subject=PCN-20201004>