

Company	Trenz Electronic GmbH
PCN Number	PCN-20250505
Title	TE0808-05 Ferrite Bead Change
Subject	BOM Change
Issue Date	2025-05-05

1 Products Affected

This change affects all Trenz Electronic TE0808-05* with a serial number greater than 968000.

2 Changes

2.1 #1 Changed ferrite bead (L1 ... L5, L7) from BKP0603HS121-T to MPZ0603S121HT000.


Type: BOM Change

Reason: EOL of component.

Impact: Increase current capability, decreased DC resistance and minor changes in electrical characteristics.

3 Method of Identification

The revision number and the serial number are shown on the top side of the PCB.



4 Production Shipment Schedule

With immediate effect this change takes place. If the changed product is not suitable for your application and still the former version of the board is needed, please contact us.

5 Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20250505)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

6 Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.