

Company	Trenz Electronic GmbH
PCN Number	PCN-20251022
Title	TE0865 Gap Filler Upgrade
Subject	BOM Change
Issue Date	2025-11-05

Products Affected

This change affects all TE0865-02 variants with preassembled heatspreader: TE0865-02-xxxxxxxK.

Affected Product	Serial Number
TE0865-02-ABI81MAK	All
TE0865-02-DGE43MAK	> 962553
TE0865-02-DGE93MAK	All
TE0865-02-FBE23MAK	All
TE0865-02-FBE83MAK	All

Changes

#1 Changed gap filler from GF3500S35-00-60-50CC to GF4500CVO-00-240-50CC.

Type: BOM Change

Reason: Improve thermal conductivity.

Impact: Improved thermal conductivity. Changed colour from blue to pink. For more detailed changes consult gap filler datasheets.

Method of Identification

The old gap filler is blue and the new is pink.

Production Shipment Schedule

This change takes place with immediate effect. If the new product is not suitable for your application and still the former version of the product is needed, please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20251022)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.