

Company	Trenz Electronic GmbH
PCN Number	PCN-20250909
Title	Cooler Hardware Improvement
Subject	Hardware Improvement
Issue Date	2025-09-09

Products Affected

This change affects following Trenz Electronic Kits:

Affected Product	Serial Number
TE0808-05-9BE21-EK	> 974528
TE0808-05-9BE81-AK	> 978188
TE0808-05-BBE81-EK	> 963156
TE0808-05-6BE81-EK	> 974547
TE0808-05-9GI81-EK	> 976701
TE0808-05-9BE81-EK	> 961573
TE0808-05-9BE84-EK	all

Changes

#1 Added orientation mark and article number (FRKK0808-05 → 34346.) at cooler.

Type: Hardware Change

Reason: Improve manufacturing process.

Impact: None. Chamfered edge shows orientation. Article number identifies component.

Method of Identification

The serial number is shown on the cooler.

Production Shipment Schedule

This change takes place with immediate effect. If the new model is not suitable for your application and still the former model of the heat spreader is needed, please contact us.

Contact Information

If you have any questions related to this PCN, please contact Trenz Electronics Technical Support at

- forum.trenz-electronic.de
- wiki.trenz-electronic.de
- support@trenz-electronic.de (subject = PCN-20250909)
- phone
 - national calls: 05741 3200-0
 - international calls: 0049 5741 3200-0

Disclaimer

Any projected dates in this PCN are based on the most current product information at the time this PCN is being issued, but they may change due to unforeseen circumstances. For the latest schedule and any other information, please contact your local Trenz Electronic sales office, technical support or local distributor.

This PCN follows JEDEC Standard J-STD-046.